From: Johnson, Nels [Nels.Johnson@aptim.com]

Sent: Saturday, October 3, 2020 1:57 PM

To: Larson, Leo M CTR (USA) [leo.m.larson.ctr@navy.mil]

CC: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) [paul.stoick@navy.mil]

Subject: [Non-DoD Source] RE: HPNS Parcel E Weekly Reports

Attachments: 500712 HPNS CTO-0024 Biweekly Status Report_10_03_20.xlsx; 501158 HPNS

CTO-4761 Biweekly Status Report_10_03_20.xlsx

Hi Leo -

Attached please find the Parcel E Bi-weekly Reports for Phases 1 and 3. If you have any questions, let me know. Thanks, Nels

NELS JOHNSON, PE

Sr Project Manager

APTIM | CoE Project Management

0 925.288.2170

(b) (6) E nels.johnson@aptim.com



4005 Port Chicago Highway, Suite 200 Concord, CA 94520

APTIM	BIWEEKLY FIELD WORK STATUS REPORT					
Project Name:	HPNS Parcel E Remedial Action; Phase 1	Date:	October 3, 2020			
Contract Number:	N62473-12-D-2005	Reporting Period:	8/22/2020 thru 10/02/2020			
Task Order Number:	CTO-0024 EMAC II		APTIM Federal Services, LLC			
Contracting Office:	VFAC Southwest Contractor Nar		1725 Duke Street, Suite 400			
Contracting Officer:	Karen Barba	Alexandria, VA 22314				
RPM	Leo Larson		Nels Johnson			
Nove Lood DDM	Doul Steink	APTIM PM	nels.johnson@aptim.com			
Navy Lead RPM	Paul Stoick		(b) (6)			
Period of Performance:	August 08, 2018 through February 08, 2021	APTIM Project No.	500712			
1. Summary of Field Work Accomplishr	nents During Reporting Period					
Work Element	Comments					
1.4 - Project Management and Admin Support	Managed overall Project scope, schedule and budge issues/aspects and path forward to Navy RPM on a September invoicing.					
3.1 thru 3.3 - Temporary Construction Facilities, Site Maintenance, Air Monitor, Survey, Radiological Controls	Maintained temporary facilities including Radiological Controls, Security, BMPs, Air Monitoring, Turbidity Curtain, Surface Water Samples, UXO and Topographic Surveys.					
	All of the Base excavations in EOS-1 and EOS-2 have been performed. There have been 3 step-out excavation and additional sampling events performed. To date a total of 25,230 BCY have been excavated from the excavation areas (22,084 BCY base and 3,146 BCY IDIQ step-outs). There are 5 excavations areas in EOS-1 and EOS-2 (of 36 total) that are awaiting confirmation results and backfill.					
	Continued Mechancial Screening Soil/Debris to less than 2" to accommodate S3 and RSY Pad Radiological processing of soil. APTIM temporarly suspended screening operations on September 11, 2020 till more material could be generated and space created.					
3.4 - Excavation; Tier 1, 2 and TPH Locations	There were approximately 60 LLROs discovered related to the above excavations or soil processing performed during the period. The initial findings of LLROs have been documented, assigned numbers and placed in locked storage pending isotopic evaluation.					
	Two existing monitoring wells were decommisioned on 9/18/2020 in order to complete Parcel E Armored Revetment activities in EOS-1 and EOS-4.					
	The Proof of Concept (S3 Soil Processing) ceased as of August 12th. ISO-Pacific demobilized their personnel and equipment in late August. APTIM began to radiologically process soil/debris using RSY Pads. The need for additional RSY Pads is critical to maintain the project schedule. APTIM began discussing this with the Navy in late June and thru July. On August 10, 2020 APTIM submitted a formal request to Contracting to use areas within RSY 3, RSY 4 and a portion of J Street. APTIM received the go ahead to use RSY 3 and 4 areas from the Navy on September 2, 2020.					
3.5 - Steam and Fuel Line Closure/Removal	No activity this period.					
3.6 - Soil Gas Survey	No activity this period.					
3.7 - Groundwater Treatment	No activity this period.					
3.8 - Soil Vapor Extraction	No activity this period.					
3.9 - Biological Coordination	As-needed weekly coordination.					
4.1 thru 4.3 Reporting	No activity this period.					



BIWEEKLY FIELD WORK STATUS REPORT

APTIM	BIWEEKLY FIELD WORK STATUS REPORT				
2. Planned Accomplishments During Next Reporting Period					
Work Element	Comments				
1.4 - Project Management and Admin Support	Manage overall Project scope, schedule and budget. Participate in Weekly QC Meeting. Continue to communicate project updates, key issues/aspects and path forward to Navy RPM on a regular basis. Respond to Mod 12 RFP (receipt pending)				
3.1 thru 3.3 - Temporary Construction Facilities, Site Maintenance, Air Monitor, Survey, Radiological Controls	Maintain temporary facilities including Radiological Controls, Security, BMPs, Air Monitoring, Turbidity Curtain, Surface Water Samples, UXO and Topographic Surveys.				
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Continue to perform excavation efforts in EOS-1 and EOS-2 Areas by performing step outs (as applicable) and subsequent backfill activities.				
3.4 - Excavation; Tier 1, 2 and TPH Locations	Continue Screening Soil/Debris to less than 2" to accomodate accomdate placement on RSY Pad for Radiological processing.				
Locations	Continue to Radiologically screen soil/debris on RSY Pads.				
	Begin to perform remedial excavation activities in EOS-4.				
3.9 - Biological Coordination	As-needed weekly coordination.				
3. Open Items:					
Status of FCRs:	There have been 8 FCRs submitted to-date on CTO0024. FCR 001, 002, 004 and 008 have been approved by the Navy. FCR 003 is currently in Navy review, FCR 005 has been canceled and FCR 006 and 007 are on hold.				
Status of Submittals:	There have been 2 submittals related to offsite borrow material that have been approved; General Fill and Drain Rock (Stanford Pile and Vulcan and Hanson Quarry Material).				

APTIM			BIWEEKLY FIELD WORK STATUS REPORT													
atus of Mo	lodifications/REAs:		Mod 12 May 20	RFP is p to avoid	neld scopioneld scopio	the Navy	v. Submined sched	tted email dule for pr	to RPM o	n 4/24/20	020 reque	sting CTC	0024 M	OD 12 ap	proval no	later tha
Product	tion Summary:															
atus of Ex	xcavation:				,084 BCY cavation s											
atus of Ba	ackfill:				l of 28 (of ading for th				ave been t	oackfilled	to date in	EOS-1 a	nd EOS-	2 areas.	Confirmat	tion side
	ackfill: arcel E Phase 1 Exc	avation S	samples	s are per					eve been t	oackfilled	to date in	EOS-1 a	nd EOS-	2 areas.	Confirmat	tion side\
atus of Ba		avation S	samples	s are per					eve been t	oackfilled	to date in	EOS-1 a	nd EOS-	2 areas. As of:	Confirmat	
		avation S	samples	s are per					EOS-4	packfilled		EOS-1 a				
IPNS Pa	arcel E Phase 1 Exc	Volume (Samples Summary EOS-1 BANK CY)	s are per	nding for the	EOS-2 BANK CY)	xcavation	n areas.	EOS-4 BANK CY)	% of	M Volume (U-1 to MU- BANK CY)	3 % of	As of: Volume (9/4/: TOTAL BANK CY)	2020 % of
IPNS Pa	Type	Volume (Summary EOS-1 BANK CY) Planne	% of	Volume (EOS-2 BANK CY)	% of	Volume (Excavat	EOS-4 BANK CY) Planne v	% of Plann(v	M Volume (Excavat v	U-1 to MU- BANK CY) Planne v	3 % of Plann{ >	As of: Volume (Excavat	9/4/ TOTAL BANK CY) Planne =	2020 % of Plann(~
IPNS Pa xcavati√√	Type Von-Rad	Volume (Excavat	EOS-1 BANK CY) Planne	% of Plann v	Volume (Excavat	EOS-2 BANK CY) Planne	% of Planne	Volume (Excavat	EOS-4 BANK CY) Planne v	% of Plann(▼	Volume (Excavat =	U-1 to MU-BANK CY) Planne v 1440	3 % of Plann(* 100.0%	As of: Volume (Excavat 1440	9/4/2 TOTAL BANK CY) Planne =	2020 % of Plann(** 100.0%
HPNS Pa	Type Non-Rad Rad Support Only	Volume (Excavat v	EOS-1 BANK CY) Planne 0 1894	% of Plann(NA 122.7%	Volume (Excavat > 0 4510	EOS-2 BANK CY) Planne V 0 3790	% of Plann(VNA 119.0%	Volume (Excavat v	EOS-4 BANK CY) Planne • 0 2295	% of Plann(▼ NA 0.0%	Volume (Excavat v 1440	U-1 to MU-BANK CY) Planne = 1440 0	3 % of Plann(v 100.0% NA	As of: Volume (Excavat > 1440 6833	9/4/2 TOTAL BANK CY) Planne = 1440 7979	2020 % of Plann(*v 100.0% 85.6%
HPNS Pa Excavati√. Main Main	Type Von-Rad	Volume (Excavat	EOS-1 BANK CY) Planne	% of Plann v	Volume (Excavat	EOS-2 BANK CY) Planne	% of Planne	Volume (Excavat	EOS-4 BANK CY) Planne v	% of Plann(▼	Volume (Excavat =	U-1 to MU-BANK CY) Planne v 1440	3 % of Plann(* 100.0%	As of: Volume (Excavat 1440	9/4/2 TOTAL BANK CY) Planne =	2020 % of Plann(** 100.0%
HPNS Pa Excavati(√ Main Main Main Main	Type Von-Rad Rad Support Only Rad w/ ESS Support	Volume (Excavat ▼ 0 2323 14649	EOS-1 BANK CY) Planne 0 1894 15447	% of Plann(+ NA 122.7% 94.8%	Volume (Excavat v 0 4510 602	EOS-2 BANK CY) Planne 0 3790 413	% of Plann(× NA 119.0% 145.8%	Volume (Excavat v 0 0	EOS-4 BANK CY) Planne ▼ 0 2295 949	% of Plann(▼ NA 0.0% 0.0%	M Volume (Excavat ▼ 1440 0	U-1 to MU- BANK CY- Planne = 1440 0	3 % of Plann(~ 100.0% NA NA	As of: Volume (9/4/ TOTAL BANK CY) Planne = 1440 7979 16809	% of Plann(v 100.0% 85.6% 90.7%
	Type Non-Rad Rad Support Only Rad w/ ESS Support Rad Support Only	Volume (Excavat ▼ 0 2323 14649 110	EOS-1 BANK CY) Planne 0 1894 15447	% of Plann(> NA 122.7% 94.8% NA	Volume (Excavat volume (602 306	EOS-2 BANK CY) Planne v 0 3790 413 0	% of Planne = NA 119.0% 145.8%	Volume (Excavat v 0 0 0 0	EOS-4 BANK CY) Planne = 0 2295 949	% of Plann(V NA 0.0% 0.0% NA NA 0.0%	M Volume (Excavat = 1440 0 0 0	U-1 to MU- BANK CY) Planne ▼ 1440 0 0 0 0	3 % of Plann(v 100.0% NA NA NA NA 100.0%	As of: Volume (Excavat = 1440 6833 15251 416	9/4/3 TOTAL BANK CY) Planne 4 1440 7979 16809	2020 % of Plann(v 100.0% 85.6% 90.7% NA

△ APTIM	BIWEEKLY FIELD WORK STATUS REPORT				
Project Name:	HPNS Parcel E Remedial Action; Phase 3	Date:	October 3, 2020		
Contract Number:	N62473-17-D-0006	Reporting Period:	8/22/2020 thru 10/02/2020		
Task Order Number:	CTO-N6247318F4761 (RADMAC II)	APTIM Federal Services, LLC			
Contracting Office:	NAVFAC Southwest	Contractor Name:	1725 Duke Street, Suite 400		
Contracting Officer:	Karen Barba		Alexandria, VA 22314		
RPM	Leo Larson	Nels Johnson			
Nove Lood DDM	Doul Steink	APTIM PM	nels.johnson@aptim.com		
Navy Lead RPM	Paul Stoick		925-787-0677		
Period of Performance:	June 29, 2018 through June 29, 2021 APTIM Project No. 501158		501158		
1. Summary of Field Work Accomplishing	nents During Reporting Period				
Work Element	Comments				
1.0 - Project Management and Admin Support	Managed overall Project scope, schedule and budget. Participated in Weekly QC Meeting. Communicated project updates, key issues/aspects and path forward to Navy RPM on a regular basis. Prepared and submitted draft schedule of values for August and September invoicing.				
2.3.1 thru 2.3.4 - Temporary Construction Facilities, Mobilization, and Site Maintenance	Maintained temporary facilities including Radiological Controls, Security, BMPs, Air Monitoring, Turbidity Curtain, Surface Water Samples, UXO and Topographic Surveys.				
2.3.5 - Excavation; Tier 1, 2 and TPH Locations; EOS-1, EOS-3 and EOS-4	Continued excavation and mechanical screening of soil within the footprint of the shoreline revetment bench in EOS-1 and EOS-2. Soil is intended to be Radiologically cleared and re-used as part of the revetment anchor bench. There is an area along the shoreline revetment bench that contains debris that has tested positive for asbestos containing materials. APTIM is working up an approach to excavate this soil/debris (<500 yds) and properly segregate, scan and dispose of the material. The Proof of Concept (S3 Soil Processing) being performed initially under CT0024 has ceased as of August 12th. ISO-Pacific demobilized their personnel and equipment in late August. APTIM began to radiologically process soil/debris using RSY Pads. APTIM received the go ahead to use RSY 3 and 4 areas from the Navy on September 2, 2020. APTIM mobilized to EOS-3 and EOS-4 the week of September 14th and began debris clearance along the shoreline.				
2.3.6 - IR-02 Nearshore Slurry Wall Construction	Completed construction of approximately 1,064 lf of Nearshore Slurry Wall and protective cap on July 8, 2020 in EOS-1 and EOS-2.				
2.3.7 - Radiological Screening of Excavated Soil, Sediment and Debris	Continued scanning of shoreline revetment bench material. There has been in excess of 150 LLROs discovered related to the revetment bench material (excavations or soil processing) performed to-date. The initial findings of LLROs have all been documented, assigned numbers and placed in locked storage pending isotopic evaluation.				
2.3.8 - Shoreline Protection and Armored Revetment	Continued construction of the Hybrid Revetment in EOS-2. Approximately 752 If of Hyrbird Revetment has been constructed, including excavation of soil/debris, placement of filter fabric, filter rock layer and light riprap layer. The final course sand layer placement is pending. This task is considered to be 80% complete. Note, this work is required to be done around low tide cycles.				
2.3.9 - Biological Coordination	As-needed weekly coordination.				
2.3.10 - Waste Loading, Hauling and Disposal	No activity this period.				
4.0 - Data Submission Reports	No activity this period.				



BIWEEKLY FIELD WORK STATUS REPORT

APTIM	BIWEEKLY FIELD WORK STATUS REPORT				
. Planned Accomplishments During Next Reporting Period					
Work Element	Comments				
1.0 - Project Management and Admin Support	Manage overall Project scope, schedule and budget. Participate in Weekly QC Meeting. Continue to communicate project updates, key issues/aspects and path forward to Navy RPM on a regular basis.				
2.3.1 thru 2.3.4 - Temporary Construction Facilities, Mobilization, and Site Maintenance	Maintain temporary facilities including Radiological Controls, Security, BMPs, Air Monitoring, Turbidity Curtain, Surface Water Samples, UXO and Topographic Surveys.				
	Continue excavation and mechanical screening of soil within the footprint of the shoreline revetment bench in EOS-1 and EOS-2. Soil is intended to be Radiologically cleared and re-used as part of the revetment anchor bench.				
2.3.5 - Excavation; Tier 1, 2 and TPH	Continue to remove debris along the shoreline in EOS-4.				
Locations; EOS-1, EOS-3 and EOS-4	Begin shoreline excavations; 7 total for approximately 1,138 BCY. Take necessary confirmation samples and backfill.				
	Begin to process EOS-4 excavated soil on RSY Pads in RSY 3 area.				
2.3.6 - IR-02 Nearshore Slurry Wall Construction	Complete as of July 8, 2020				
2.3.8 - Shoreline Protection and Armored Revetment	Complete construction of the Hybrid Revetment in EOS-2 by placing the 2-foot course sand layer. Begin construction of the Hybrid Revetment in EOS-3 and EOS-4. This work is required to be done around low tide cycles.				
3.9 - Biological Coordination	As-needed weekly coordination.				
3. Open Items:					
Status of FCRs:	There have no FCRs submitted to-date on CTO4761.				
Status of Submittals:	There have been 7 submittals to-date approved by the Navy that are related to rebar for seawall, shoring design, slurry wall mix, import fill (General, Drain Rock, Armor Stone), and slurry wall implementation. Submittal 008 (Filter Fabric) submitted for information purposes and Submittal 009 (CPT Investigation) was submitted and is pending Navy approval.				

APTIM	BIWEEKLY FIELD WORK STATUS REPORT
Status of Modifications/REAs:	CTO 4716 MOD 06 was received on June 4, 2020.
4. Production Summary:	
Status of Excavation:	Four of the eleven Tier 1, 2 and TPH tidal excavations have been completed; excavated, sampled and backfilled.
Status of Nearshore Slurry Wall:	The temporary sheetpile shoring installation was completed on June 9th (approximately 1,070 lf) and the construction of the Nearshore Slurry Wall and protective cap was completed on July 8th.